Trinity Consultants
5305 West Village Parkway, Suite 1, Rogers, AR / P 501.225.6400 / **trinityconsultants.com**

June 26, 2025

EPA Region 6
1201 Elm Street
Dallas, TX 75202

RE: MACT WWWW Semi-Annual Report
Crane Composites; AFIN 16-00222; Permit No. 2111-AOP-R6

Dear Staff:

As required by 40 CFR 63.5910(c), this report fulfills the requirements to submit periodic reports for the reporting period of December 1, 2024 through May 31, 2025 as required by 40 CFR 63, Subpart WWWW (MACT WWWW). During this reporting period the facility operated under Permit No. Permit No. 2111-AOP-R6.

The reporting requirements of MACT WWWW are listed below with the required information provided in italic font below each requirement.

63.5910(c). The compliance report must contain the information in paragraphs (c)(1) through (6) of this section:

63.5910(c)(1). Company name and address.

Crane Composites, 8500 CW Post Road, Jonesboro, AR 72401

63.5910(c)(2). Statement by a responsible official with that official's name, title, and signature, certifying the truth, accuracy, and completeness of the content of the report.

A certification statement is provided through certification to CEDRI or ADEQ's ePortal.

63.5910(c)(3). Date of the report and beginning and ending dates of the reporting period.

Dates are provided above.

63.5910(c)(5). If there are no deviations from any organic HAP emissions limitations (emissions limit and operating limit) that apply to you, and there are no deviations from the requirements for work practice standards in Table 4 to this subpart, a statement that there were no deviations from the organic HAP emissions limitations or work practice standards during the reporting period.

There were no deviations from the requirements for work practice standards in Table 4.

63.5910(c)(6). If there were no periods during which the continuous monitoring system (CMS), including a continuous emissions monitoring system (CEMS) and an operating parameter monitoring system were out of

control, as specified in §63.8(c)(7), a statement that there were no periods during which the CMS was out of control during the reporting period.

There were no out of control periods during the reporting period.

63.5910(d). For each deviation from an organic HAP emissions limitation (i.e., emissions limit and operating limit) and for each deviation from the requirements for work practice standards that occurs at an affected source where you are not using a CMS to comply with the organic HAP emissions limitations or work practice standards in this subpart, the compliance report must contain the information in paragraphs (c)(1) through (4) of this section and in paragraphs (d)(1) and (2) of this section. This includes periods of startup, shutdown, and malfunction.

There were no deviations from an organic HAP emissions limitation or from the requirements for work practice standards at an affected source not using a CMS to comply with organic HAP emissions limitations or work practice standards.

63.5910(e). For each deviation from an organic HAP emissions limitation (i.e., emissions limit and operating limit) occurring at an affected source where you are using a CMS to comply with the organic HAP emissions limitation in this subpart, you must include the information in paragraphs (c)(1) through (4) of this section and in paragraphs (e)(1) through (12) of this section. This includes periods of startup, shutdown, and malfunction.

There were no deviations from an organic HAP emissions limitation at an affected source using a CMS to comply with organic HAP emissions limitations.

63.5910(h). Submit compliance reports and startup, shutdown, and malfunction reports based on the requirements in table 14 to this subpart, and not based on the requirements in §63.999.

As required by 40 CFR 63.999(c)(6)(i), this paragraph documents daily average values of monitored parameters (RTO temperature) for any days when the daily average value was below the set point required to maintain 95% destruction of volatile organic compounds or the data availability requirements were not met.

Based on a review of the RTO measurements recorded during the past 6 months, this facility had 0 days when the daily average RTO temperature was below the set point of 1,400 °F.

Based on a review of the RTO temperature measurements recorded during the past 6 months, this facility had 0 days when the data availability requirements were not met.

Sincerely,
TRINITY CONSULTANTS

Amy Moore
Managing Consultant

cc: Mr. Shannon G. Lynn, P.E., Trinity Consultants (Little Rock, AR)
Mr. Heinz Braun, Arkansas Division of Environmental Quality (North Little Rock, AR)